

**Equipment: RWC2020A, Interference Generator**

## Revision History

Version	Date	Description
<b>Version 1.010</b>	20 Dec.2021	1. Enhanced encryption key for firmware upgrade.
<b>Version 1.001</b>	20 Sep.2021	1. The DHCP protocol has been upgraded to improve the interoperability of Ethernet connections.